

Service Bulletin

EASA.21J.603

Doc.: SB-MD02-004 Date: 02.06.2020 Page: 1 of 2

Recommended Service Bulletin

SB-MD02-004

1 Technical Details

1.A Category

Recommended

1.B Subject

Replacement and use of a modified glow plug igniter

1.C Affected

MD-TJ42; All S/N

1.D Reason

Improved start-up behaviour with higher reliability.

1.E Time of Compliance

N/A

1.F Reference

/1/ MD02-OMM-70-001 Operation and Maintenance Manual MD-TJ42

1.G Mass and CG

Not affected

1.H Actions

Change of old Igniter against modified Igniter according to chapter 7.5.1 in /1/.

1.I Interchangeability and Mixability of Parts

The old Igniter (P/N 04-3187) can be replaced with the modified Igniter (P/N MD02-74-20-01).

1.J Approval

The technical content of this document is approved under the authority of DOA ref. EASA.21J.603.

1.K Appendices

None.



Service Bulletin

EASA.21J.603

Doc.: SB-MD02-004 Date: 02.06.2020 Page: 2 of 2

2 Planning Information

2.A Material

- Modified Igniter (P/N MD02-74-20-01)
- Cotter pin (P/N 04-3466)

2.B Special Tools

None.

3 Remarks

3.A Remarks

None.

4 Approval Signatures

Remark: With the signature the **HOA** confirms that the technical content of the Service Bulletin has been checked and the change described is approved.

	Approved by HOA
(Head of Office of Airworthiness)	on: 25.05.2020 under approval No.: MCA-2020-005
Initial Issue	