



**M&D Flugzeugbau GmbH & Co. KG**  
 Streeker Str. 5b, D-26446 Friedeburg  
 Tel.: +49 4465 97878 0, Fax: +49 4465 97878 99  
 www.md-flugzeugbau.de info@md-flugzeugbau.de

Type: **JS-MD Single**

Model: **JS-MD 3**

TCDS No.: **EASA.A.616**

**EASA.21J.603**

**SB Overview**

Date: **07.09.2021**

SB No.	Rev.	Category	Date of Issue	AD No.	Affected Models and Serial No.	Subject	Time of Compliance	Remarks
SB-MD10-001	00	MSB	08.07.2020	N/A	All JS-MD 3 with jet sustainer installed up to S/N 3.MD083	EGT Sensor Location	within 90 days after the effective date of this SB	MD10-WOI-77-001
SB-MD10-002	00	RSB	04.08.2020	N/A	All JS-MD 3 up to and including S/N 3.MD079	Tip Ventilation Upgrade	N/A	
SB-MD10-003	00	RSB	28.09.2020	N/A	all	Canopy Gas Strut Inspection	within 90 days after the effective date of this SB	N/A
SB-MD10-004	00	RSB	01.12.2020	N/A	3.MD003 up to and including 3.MD092	Belly-Hook Release Cable Replacement	within the next 3 months OR during the next Annual Inspection, whichever comes first	MD10-WOI-53-001
SB-MD10-005	00	RSB	01.12.2020	N/A	all	Tailwheel Main Shaft Locknut Inspection	within the next 3 months from OR during the next Annual Inspection, whichever comes first	MD10-WOI-32-001
SB-MD10-006	00	RSB	31.03.2021	N/A	All JS-MD3 with parking brake pin installed	Brake System In-line Accumulator Installation	within the next 3 months OR if current brake force is unsatisfactory	
SB-MD10-007	00	RSB	31.03.2021	N/A	3.MD001 to 3.MD007; 3.MD009 to 3.MD015; 3.MD017 to 3.MD064; 3.MD067	Stabilizing of Tailwheel Cable	Inspection before next flight	



**M&D Flugzeugbau GmbH & Co. KG**  
 Streeker Str. 5b, D-26446 Friedeburg  
 Tel.: +49 4465 97878 0, Fax: +49 4465 97878 99  
 www.md-flugzeugbau.de info@md-flugzeugbau.de

Type: **JS-MD Single**

Model: **JS-MD 3**

TCDS No.: **EASA.A.616**

**EASA.21J.603**

**SB Overview**

Date: **07.09.2021**

SB No.	Rev.	Category	Date of Issue	AD No.	Affected Models and Serial No.	Subject	Time of Compliance	Remarks
SB-MD10-008	00	RSB	07.09.2021	N/A	3.MD001 – 3.MD095	Jet Main Fuel Line Damaged By Pylon	It is recommended that this Service Bulletin be completed at the next scheduled maintenance period or phase inspection, or sooner if deemed necessary by the owner.	
SB-MD10-009	00	RSB	07.09.2021	N/A	3.MD087 – 3.MD108	Air Sense Probes Dimension Inspection	It is recommended that this Service Bulletin be completed at the next scheduled maintenance period or phase inspection, or sooner if deemed necessary by the owner.	