| | | | |
|---|---|---|---|
| M+D FLUGZEUGBAU | **M&D Flugzeugbau GmbH & Co. KG, Streeker Str. 5b, D-26446 Friedeburg**<br>**Tel.: +49 4465 97878 0, Fax: +49 4465 97878 99**<br>**www.md-flugzeugbau.de info@md-flugzeugbau.de** | Type: | **MD-TJ42** |
| | | TCDS No.: | **EASA.E.099** |
| EASA.AP175 | **SB Overview** | **Date: 24.02.2016** | |

| SB No. | Rev. | Category | Date of Issue | AD No. | Affected Models and Serial No. | Subject | Time of Compliance | Remarks |
|---|---|---|---|---|---|---|---|---|
| SB-MD02-001 | 0 | RSB | 28.01.2016 | | up to and including S/N MD02-0048 | Conversion of Pre-Type-Certificate (Pre-TC) engines to the certified standard | N/A | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |