

# **Mandatory Service Bulletin SB-MD10-014**

## **1 Technical Details**

### **1.A Category**

Mandatory

### **1.B Subject**

Data Plate Replacement for S/N 3.MD015

### **1.C Affected**

JS-MD Single / JS-MD 3 / 3.MD015

### **1.D Reason**

The old data plate needs to be replaced with the new data plate from M&D Flugzeugbau GmbH & Co.KG.

### **1.E Time of Compliance**

N/A

### **1.F Reference**

/1/ MD10-WOI-00-015.1 Work Instructions for Data Plate Replacement

### **1.G Mass and CG**

Not affected.

### **1.H Actions**

Replace the old data plate with the new data plate from M&D Flugzeugbau GmbH & Co.KG. according to the applicable Work Instructions /1/.

### **1.I Interchangeability and Mixability of Parts**

None

### **1.J Approval**

The technical content of this document is approved under the authority of the DOA ref. EASA.21J.603.

**1.K Appendices**

None.

**2 Planning Information**

**2.A Material**

- 2.5mm round head aluminium rivets

**2.B Special Tools**

None.

**3 Remarks**

The measure can be performed and released by a competent person as pilot-owner maintenance according to European Union Commission Regulation (EC) 1321/2014 Appendix II to Annex Vb (Part-ML). In countries outside the scope of EC 1321/2014 the corresponding national rules shall apply.

Work instruction and Parts can be obtained from

M&D Flugzeugbau GmbH & Co. KG  
 Streeker Straße 5B  
 26446 / Friedeburg  
 Phone: +49 44 65 97878 0 / Fax: +49 44 65 97878 99  
 E-Mail: info@md-flugzeugbau.de

Please indicate S/N and operating time of your aircraft in your inquiry.

**4 Approval Signatures**

**Remark:** With the signature, the **HOA** confirms that the technical content of the Service Bulletin has been checked and the change described is approved.

Date: 24.10.2024  (Head of Office of Airworthiness)	Approved by HOA  on: 24.10.2024 under approval No.: MCA-2024-002
<b>Initial Issue</b>	