

Service Letter

SL-MD22-001

1 Technical Details

This service letter is to inform owners, operators and maintenance organisations that the Type Certificate (TC) of the **PSR T01 Turbine Engine** has been transferred from **Draline b.v.** to **M&D Flugzeugbau GmbH & Co. KG**. See TCDS EASA.E.108 Issue 02.

Continuous airworthiness issues will be managed by the Design Organisation EASA.21J.603 of M&D Flugzeugbau GmbH from now on.

1.A Products affected

All PSR T01 engines.

1.B Subject

Transfer of ownership and design responsibility of TC EASA.E.108 Issue 02 for all PSR T01 engines

1.C Reason

Mutual agreement between the two partners

1.D Information

All inquiries and continuous airworthiness matters are now handled by M&D Flugzeugbau GmbH.

General Contact Information:

M&D Flugzeugbau GmbH & Co. KG

Streeker Straße 5B

26446 Friedeburg

Germany

Phone: +49 44 65 97878 0

Fax: +49 44 65 97878 99

E-Mail: info@md-flugzeugbau.de

Occurrence Reporting:

Submit occurrence reports via email (ocr@md-flugzeugbau.de) or postal to M&D Flugzeugbau GmbH & Co. KG, Streeker Str. 5b, D-26446 Friedeburg.

Please find a template for Occurrence Report Form, on the Website of M&D Flugzeugbau GmbH under Services.

Applicable Manuals:

The currently applicable manuals for the engine are published on the website of M&D Flugzeugbau GmbH under Services, Technical Information.

Contact for inquiries:

Phone: +49 44 65 97878 0 / Fax: +49 44 65 97878 99

E-Mail: info@md-flugzeugbau.de

Please indicate S/N and operating time of your engine in your inquiry.

1.E References

TCDS EASA.E.108 Issue 02.

List of applicable manuals: MD22-LAM-00-001-R00

MD-21J-FO-CAW-004 Occurrence Report

1.F Appendices

List of applicable manuals: MD22-LAM-00-001-R00

2 Other Details

N/A