



M&D Flugzeugbau GmbH & Co. KG
 Streeker Str. 5b, D-26446 Friedeburg
 Tel.: +49 4465 97878 0, Fax: +49 4465 97878 99
 www.md-flugzeugbau.de info@md-flugzeugbau.de

Type:	JS-MD Single
Model	JS-MD 3
TCDS No.:	EASA.A.616
Date:	31.03.2021

EASA.21J.603

SB Overview

SB No.	Rev.	Category	Date of Issue	AD No.	Affected Models and Serial No.	Subject	Time of Compliance	Remarks
SB-MD10-001	00	MSB	08.07.2020	N/A	All JS-MD 3 with jet sustainer installed up to S/N 3.MD083	EGT Sensor Location	within 90 days after the effective date of this SB	MD10-WOI-77-001
SB-MD10-002	00	RSB	04.08.2020	N/A	All JS-MD 3 up to and including S/N 3.MD079	Tip Ventilation Upgrade	N/A	
SB-MD10-003	00	RSB	28.09.2020	N/A	all	Canopy Gas Strut Inspection	within 90 days after the effective date of this SB	N/A
SB-MD10-004	00	RSB	01.12.2020	N/A	3.MD003 up to and including 3.MD092	Belly-Hook Release Cable Replacement	within the next 3 months OR during the next Annual Inspection, whichever comes first	MD10-WOI-53-001
SB-MD10-005	00	RSB	01.12.2020	N/A	all	Tailwheel Main Shaft Locknut Inspection	within the next 3 months from OR during the next Annual Inspection, whichever comes first	MD10-WOI-32-001
SB-MD10-006	00	RSB	31.03.2021	N/A	All JS-MD3 with parking brake pin installed	Brake System In-line Accumulator Installation	within the next 3 months OR if current brake force is unsatisfactory	
SB-MD10-007	00	RSB	31.03.2021	N/A	3.MD001 to 3.MD007; 3.MD009 to 3.MD015; 3.MD017 to 3.MD064; 3.MD067	Stabilizing of Tailwheel Cable	Inspection before next flight	