



M&D Flugzeugbau GmbH & Co. KG
 Streeker Str. 5b, D-26446 Friedeburg
 Tel.: +49 4465 97878 0, Fax: +49 4465 97878 99
 www.md-flugzeugbau.de info@md-flugzeugbau.de

Type:

JS-MD Single

Model

JS-MD 1C

TCDS No.:

EASA.A.616

EASA.21J.603

SB Overview

Date:

28.03.2022

SB No.	Rev.	Category	Date of Issue	AD No.	Affected Models and Serial No.	Subject	Time of Compliance	Remarks
SB-MD01-001	00	MSB	17.06.2020	N/A	JS-MD 1C, All S/N with MD-TJ 42 jet engine installed	Jet System Engine Wiring Loom Damage Inspection and Repair	Action 1: 30 d / 5 engine cycles Action 2: with next annual inspection Action 3: N/A Action 4: every 25 flight hrs	
SB-MD01-003	00	MSB	25.01.2022	N/A	JS-MD 1C, All S/N with engine installed up to S/N 1C.MD123	Jet System Engine Fuel line replacement	With the next annual inspection or when 8 year replacement of start line and fuel line rubber is due, whichever comes first.	Highly Recommended
SB-MD01-004	01	MSB	10.03.2021	EASA AD 2021-0070	JS-MD 1C, All S/N	Inspection of Airbrake Blade 3 (bottom blade)	Inspection before next flight. If a non-conformance is identified, rectification is required before next flight.	
SB-MD01-005	01	OSB	26.03.2021	N/A	JS-MD 1C, All S/N	Tip Drain & Filling Cap Installation	N/A	