

List of applicable Manuals / ICA¹

1. Document Management

1.1. List of Revisions

| Rev. | Date | Description | Author | Affected Sections / Pages |
|------|------------|--|----------------------|---------------------------|
| 00 | 20.06.2018 | Initial Issue | Y. Heibel | All |
| 01 | 04.07.2018 | New revisions of sections of AFM & AMM | Y. Heibel | All |
| 02 | 18.09.2018 | Table refitted, new revisions of sections 0, 5, 9 of AMM | Y. Heibel | All |
| 03 | 18.12.2018 | Revision of ARM updated | Y. Heibel | All |
| 04 | 02.09.2019 | Addition of Manuals for Model JS-MD 3; new Issue of Aircraft Repair Manual; modified layout, small corrections | C. Schoberth | All |
| 05 | 09.07.2020 | Minor revisions to JS-MD 1C AMM, Updated to new form revision | P. Goralski | 4 |
| 06 | 19.08.2020 | Adjust TBO and Inspection intervals and Maintenance Schedule in AMM Jet Supplement of JS-MD 1C and JS-MD 3 | P. Goralski | 5, 6 |
| 07 | 09.12.2020 | New issues of AFM and AMM for JS-MD 3 added | K. Kemke | 6 |
| 08 | 20.01.2021 | Type Def. Reference corrected; Release date of AFM and AMM for JS-MD 3 added | K. Kemke | 1, 6 |
| 09 | 12.10.2021 | New issue of ARM added, Added Manuals of JS-MD 3 RES, see chapter 3.4; Updated Form layout to current revision | K. Kemke, P.Goralski | Sec. 1.3, 3.1 and 3.4 |
| 10 | 14.10.2021 | Correction of issue dates and revision list; Layout adjustments | P. Goralski | Sec 3.1 and 3.4 |
| 11 | 01.12.2021 | New issues of Jet Sustainer Flight Manual Supplement for JS-MD 1C and JS-MD 3 added | P. Goralski | Sec. 3.2 and 3.3 |
| 12 | 01.12.2023 | Manuals for JS-MD 3 RES updated | M. Schwarz | 3.1 and 3.4 |
| 13 | 24.04.2025 | Manuals for JS-MD 3 RES updated | K. Schutte | 3.4 |
| 14 | 28.05.2025 | AFM Supplement for JS-MD 3 RES updated | K. Schutte | 3.4 |

¹ Instructions for Continuing Airworthiness

| | | | | |
|----|------------|---|------------|------------------------------|
| 15 | 17.07.2025 | AFM Supplement, AMM Supplement and AFM for JS-MD 3 RES updated | K. Schutte | 3.4 |
| 16 | 29.01.2026 | AMM, AMM Supplement, AFM, AFM Supplement updated for JS-MD 3 RES | N. Aucamp | 3.4 |
| 17 | 08.05.2026 | Aircraft Repair Manual AMM, AMM Supplement, AFM, AFM Supplement for JS-MD 3 RES | K. Schutte | Section 3.1.1 Section 3.4 |

Unless impracticable due to the scope of the revision, the affected text will be marked by a black vertical line on the right-hand side of the page.

1.2. List of Validity

| Rev. | Valid for / Restrictions | Type Def. Reference |
|------|--------------------------|---------------------|
| 17 | JS-MD Single | EASA.A.616 |

1.3. Document Preparation

The **DE/CVE** prepares the form and content of the document according to section 1.1 and 1.2 and signs for correctness and completeness.

| | Function | Digital Signature |
|----------|----------|-------------------|
| Prepared | DE/CVE | |

2. Contents

| | | |
|--------|---|---|
| 1. | Document Management..... | 1 |
| 1.1. | List of Revisions | 1 |
| 1.2. | List of Validity | 2 |
| 1.3. | Document Preparation..... | 2 |
| 2. | Contents | 3 |
| 3. | JS-MD Single (EASA.A.616)..... | 4 |
| 3.1. | All Models..... | 4 |
| 3.1.1. | Aircraft Repair Manual..... | 4 |
| 3.2. | JS-MD 1C..... | 5 |
| 3.2.1. | Aircraft Flight Manual / Jet Sustainer Flight Manual Supplement | 5 |
| 3.2.2. | Aircraft Maintenance Manual / Jet Sustainer Maintenance Manual Supplement | 6 |
| 3.3. | JS-MD 3 | 7 |
| 3.3.1. | Aircraft Flight Manual / Jet Sustainer Flight Manual Supplement | 7 |
| 3.3.2. | Aircraft Maintenance Manual / Jet Sustainer Maintenance Manual Supplement | 7 |
| 3.4. | JS-MD 3 RES | 8 |
| 3.4.1. | Flight Manual / Self Launcher Flight Manual Supplement | 8 |
| 3.4.2. | Maintenance Manual / Self Launcher Maintenance Manual Supplement | 9 |

3. JS-MD Single (EASA.A.616)

3.1. All Models

3.1.1. Aircraft Repair Manual

| Product | Manual Number | Issue | | Title | Section | | | Note |
|--------------------------------------|-----------------|-------|------------|------------------------|---------|------|------------|--|
| | | No. | Date | | No. | Rev. | Date | |
| JS-MD 1C, JS-MD 3, JS-MD 3 RES | MD01-ARM-00-001 | 06 | 07.04.2026 | Aircraft Repair Manual | 2.2.2 | 00 | 07.04.2026 | Editorial updates in Section 2.2.2, KDU 9001 typo 100 g/m ² corrected to 300 g/m ² . |

3.2. JS-MD 1C

3.2.1. Aircraft Flight Manual / Jet Sustainer Flight Manual Supplement

| Product | Manual Number | Issue | | Title | Section | | | Note |
|----------|-----------------|-------|------------|--|---------|------|------------|---|
| | | No. | Date | | No. | Rev. | Date | |
| JS-MD 1C | MD01-AFM-00-001 | 02 | 14.09.2017 | Aircraft Flight Manual | 0 | 02 | 22.06.2018 | Table of contents, effective sections |
| | | | | | 2 | 02 | 22.06.2018 | Correction of cross reference |
| | | | | | 11 | 01 | 22.06.2018 | Inclusion of empty page |
| | | | | | 12 | 00 | 22.06.2018 | Contact info |
| JS-MD 1C | MD01-AFM-00-002 | 03 | 02.11.2021 | Jet Sustainer Flight Manual Supplement | All | 00 | 02.11.2021 | Time limit for max. RPM added, EGT limit during start-up corrected, Layout of the cockpit placards amended, editorial changes |

3.2.2. Aircraft Maintenance Manual / Jet Sustainer Maintenance Manual Supplement

| Product | Manual Number | Issue | | Title | Section | | | Note |
|----------|-----------------|-------|------------|---|---------------|------|------------|--|
| | | No. | Date | | No. | Rev. | Date | |
| JS-MD 1C | MD01-AMM-00-001 | 02 | 14.09.2017 | Aircraft Maintenance Manual | 0 | 04 | 08.07.2020 | Updates to section 2,3,4 and Table of contents |
| | | | | | 2 | 01 | 08.07.2020 | New Beringer Wheel Reference added |
| | | | | | 3 | 01 | 08.07.2020 | Airbrake Deflection Tolerance changed |
| | | | | | 4 | 01 | 08.07.2020 | Wording for unscheduled maintenance checks and added Section 4.3.5. |
| | | | | | 5 | 01 | 17.09.2018 | Wording for given reference document changed |
| | | | | | 9 | 01 | 17.09.2018 | Wording for given reference document changed |
| | | | | | 11 | 01 | 16.11.2017 | Change of Figure 11.2.1.2 (Cockpit Loads) |
| | | | | | 16 | 00 | 02.07.2018 | Contact info |
| | | | | | Appendix A | 01 | 09.11.2017 | Format of annual inspection list changed: Page A-1 through A-8 |
| JS-MD 1C | MD01-AMM-00-002 | 02 | 14.09.2017 | Jet Sustainer Maintenance Manual Supplement | Overview Page | 01 | 06.08.2020 | Added DOA reference. |
| | | | | | 0 | 03 | 06.08.2020 | Added chapter record of Issues and adjust list of effective sections |
| | | | | | 4 | 01 | 06.08.2020 | Correction of TBO and inspection interval |
| | | | | | 6 | 01 | 06.08.2020 | Revised Maintenance Schedule |
| | | | | | 15 | 00 | 03.07.2018 | New Chapter; Contact info added |
| | | | | | Appendix A | 01 | 17.11.2017 | Change of table format "Annual Inspection Checklist" (page A-1) |

3.3. JS-MD 3

3.3.1. Aircraft Flight Manual / Jet Sustainer Flight Manual Supplement

| Product | Manual Number | Issue | | Title | Section | | | Note |
|---------|-----------------|-------|------------|--|---------|------|------------|---|
| | | No. | Date | | No. | Rev. | Date | |
| JS-MD 3 | MD10-AFM-00-001 | 01 | 14.02.2020 | Aircraft Flight Manual | All | 00 | 14.02.2020 | Refer to Record of Revision in AFM (Release date: 08.12.2020) |
| JS-MD 3 | MD10-AFM-00-002 | 01 | 11.08.2021 | Jet Sustainer Flight Manual Supplement | 0 | 01 | 02.11.2021 | List of effective sections adjusted |
| | | | | | 2 | 01 | 02.11.2021 | Time limit for max. RPM added, EGT limit during start-up corrected, Layout of the cockpit placards amended, Editorial changes (<i>This note includes amendments from I01 R00</i>) |
| | | | | | 4 | 01 | 02.11.2021 | Audio Buzzer signal descriptions amended |

3.3.2. Aircraft Maintenance Manual / Jet Sustainer Maintenance Manual Supplement

| Product | Manual Number | Issue | | Title | Section | | | Note |
|---------|-----------------|-------|------------|---|---------------|------|------------|---|
| | | No. | Date | | No. | Rev. | Date | |
| JS-MD 3 | MD10-AMM-00-001 | 01 | 14.02.2020 | Aircraft Maintenance Manual | All | 00 | 14.02.2020 | Refer to Record of Issues in AMM (Release date: 08.12.2020) |
| JS-MD 3 | MD10-AMM-00-002 | 00 | 14.03.2019 | Jet Sustainer Maintenance Manual Supplement | Overview Page | 01 | 06.08.2020 | Added DOA reference. |
| | | | | | 0 | 01 | 06.08.2020 | Adjustment of revision list |
| | | | | | 4 | 01 | 06.08.2020 | Correction of TBO and inspection interval |
| | | | | | 6 | 01 | 06.08.2020 | Revised Maintenance Schedule |

3.4. JS-MD 3 RES

3.4.1. Flight Manual / Self Launcher Flight Manual Supplement

| Product | Manual Number | Issue | | Title | Section | | | Note |
|-------------|-----------------|-------|------------|--------------------------------------|---------|------|------------|---|
| | | No. | Date | | No. | Rev. | Date | |
| JS-MD 3 RES | MD11-AFM-00-001 | 01 | 29.01.2026 | Aircraft Flight Manual | 0-7 | 02 | 29.01.2026 | General revision updates RES reactivated 15m SL withdrawn Approximate empty weight (RES, no HV batteries), minimum wing load and maximum wing load updated Updated MNW weights Caution note updated to include max no water weight limitations Note added regarding permitted operating modes per wingspan configuration Updated approved rope length Limitations placard updated Added MC CB Added clarification on Pure vs Sustainer vs Self-launcher Added clarification on cockpit mass in relation to MNW |
| JS-MD 3 RES | MD11-AFM-00-002 | 05 | 25.03.2026 | JS-MD 3 RES Flight Manual Supplement | All | 00 | 25.03.2026 | Revision based on LBA feedback |

List of applicable Manuals / ICA

EASA.21J.603

Doc.: MD01-LAM-00-001-R17

Date: 08.05.2026

Page: 9 of 9

3.4.2. Maintenance Manual / Self Launcher Maintenance Manual Supplement

| Product | Manual Number | Issue | | Title | Section | | | Note |
|-------------|-----------------|-------|------------|--|---------|------|------------|--------------------------------|
| | | No. | Date | | No. | Rev. | Date | |
| JS-MD 3 RES | MD11-AMM-00-001 | 05 | 17.03.2026 | JS-MD 3 RES Aircraft Maintenance Manual | All | 00 | 17.03.2026 | RES Reactivation |
| JS-MD 3 RES | MD11-AMM-00-002 | 05 | 17.03.2026 | JS-MD 3 RES Aircraft Maintenance Manual Supplement | All | 00 | 17.03.2026 | Revision based on LBA feedback |