				M&D Flugzeugbau GmbH & Co. KG Streeker Str. 5b, D-26446 Friedeburg Tel.: +49 4465 97878 0, Fax: +49 4465 97878 99 www.md-flugzeugbau.de info@md-flugzeugbau.de			Type: Model	MD-TJ Series Engines MD-TJ42
M+D FLUGZEUGBAU							TCDS No.:	EASA.E.099
EASA.21J.603				SB Overview			Date:	18.08.2022
SB No.	Rev.	Category	Date of Issue	AD No.	Affected Models and Serial No.	Subject	Time of Compliance	Remarks
SB-MD02-001	00	RSB	28.01.2016		up to and including S/N MD02-0048	Conversion of Pre-Type-Certificate (Pre-TC) engines to the certified standard	N/A	
SB-MD02-002	00	OSB	21.05.2020		up to and including S/N MD02-0122	Working Instructions for modifying the O-Ring Groove at the Air Intake	N/A	
SB-MD02-004	00	RSB	02.06.2020		All S/N	Replacement and use of a modified glow plug igniter	N/A	
SB-MD02-005	03	RSB	18.08.2022		All S/N	Exchange of Fuel Fitting with a AN threaded fitting or metric fitting with integrated fuel filter	N/A	